

HANDLING IN PREPARATION OF MEASURING THE GARMENTS

- Lay garment out flat and face up, or face down depending on the measurement being taken.
- Garment must be buttoned or zipped unless otherwise specified
- Garment with non closure must be overlapped as specified
- Remove shoulder pads if not permanent
- Area of garment to be measured must lay flat and smooth without folds and hidden wrinkles
- For relaxed measurements, smooth without slack, but do not stretch or pull out.
- Stretched measurements are stretched to full extension of fabric
- Extended minimum measurements will be fully extended until minimum measurement is reached without rupturing seams and without distorting garments at specified points.